


# OPERATOR'S MANUAL

## StudPro LiteXI

### *Pin Welder*



**Stud Welding  
Products, Inc.**

your number one stud

# CONTENTS

---

<u>Description</u>	<u>Pages</u>
Safety	2
Specifications and Features	3
Product Components	4-5
Screen Operation	6-8
Setup and Welding	9-11
CD Gun Exploded View	12
CD Accessories	13-15

# SAFETY

---

## Read the safety notices before operating welder

### Electrical

- Due to potential dangerous electrical input and output the **equipment must be disconnected from all incoming power when servicing. Do not operate the equipment with the outer cover removed or with the case open.**
- Capacitors store electrical energy, completely discharge before performing any maintenance.
- Do not use fluids to clean electrical components as these may penetrate the electrical system and cause shorts.
- Connection of the unit into service must be in accordance with the setup procedures as detailed in this manual. Operation of this equipment must be in accordance with all local, regional, and national safety codes.



### Fire

- During welding, small particles of hot metal can be expelled. Ensure that no combustible materials are near the welding area.

### Personal Safety

- Arc rays can burn eyes and skin. Wear protective clothing and eye protection when welding.
- Loud noises from welding can damage hearing. Wear earplugs or other protective gear, if applicable.
- Fumes and gases expelled during welding can be health hazards. Make sure welding is done in a well-ventilated area.
- Hot metal splatter can cause fires and burns. Wear protective clothing, work in an area free of combustible materials, and have a fire extinguisher nearby.



### Maintenance

- All cables must be inspected regularly to ensure that no danger exists from damaged insulation or unsafe electrical connections. Take special note of the cables near the stud gun, this is where maximum wear occurs.

### Training

- Use of this equipment must be limited to authorized personnel only. They must be adequately trained, and have read and understood everything in this manual.
- The manual must be available to operators at all times.

### Installation

- Select a site which is capable of supporting the weight of the equipment.
- Select a site which is clear from heavy foot traffic areas to avoid tripping hazards.
- Select a site that prevents cable damage from equipment and vehicles.
- Do not hang connecting cables over sharp edges or place near heat sources.

# SPECIFICATIONS AND FEATURES

## Model: StudPro LiteXi

The StudPro LiteXi incorporates the latest solid state technology into a compact, rugged, and portable CD Pin Welder. This system has the capacity to weld CD pins and cupped head pins up to 10-gauge as well as CD Studs up to #10.

## Specifications

SPECS	StudPro LiteXi WELDER
SIZE	12.5" L x 10.1" W x 6.0" H 318mm x 257mm x 152mm
WEIGHT (Power Supply Only)	10.2 lbs. (4.6kg)
CAPACITANCE/ENERGY	100,000µF/500Ws
WELD RANGE	Weld Pins - Up to 10 gauge CD Studs - Up to #10
DUTY CYCLE	15-30 pins per minute
PRIMARY POWER	85-250 VAC, 1.5-0.5A, 50/60Hz
CHARGE VOLTAGE	35-100 VDC

\* Specifications are subject to change without prior notification

## Features

- Less than 1 second recharge time for pin welding
- Intuitive Touchscreen Interface with preset values for fast, accurate, and repeatable weld settings
- Set-Point Discharge: Unit discharges directly to a new set point without needing to discharge completely
- Universal Input Voltage: Plug and play, no need to re-tap the machine for 110V or 220V input voltages
- Low input voltage capability enables operation with long extension cords
- Contact and Trigger indicators for fast troubleshooting of hand tool and weld cable maintenance issues
- Thermal and Voltage protection indicators to protect the unit from damage due to overheating or poor input power
- Increased airflow for improved efficiency and duty cycle
- Rigid internal construction minimizes the possibility of components coming loose during rough handling or operation
- Hand tool has been ergonomically designed to reduce operator fatigue for increased welding efficiency
- Hand tool has an adjustable internal spring to apply the correct spring pressure for every welding application
- Hand tool can be configured for B collets, CI (Collet Inserts), Euro collets, or standard tapered chucks

# PRODUCT COMPONENTS


---

## Top Panel



Touchscreen Display

## Top Open View



Control Board

SCR

Capacitor

Resistor

# PRODUCT COMPONENTS

---

## Front Panel View




## Side Panel View




# SCREEN OPERATION

## Stud Preset Screen



## Voltage Preset Screen



# SCREEN OPERATION

---


## Stud Counter Screen

Stud Count



Stud Counter Reset

## Resetting the Stud Counter



- While on the stud counter screen, press the RESET tab located at the bottom of the screen.
- The screen will then prompt the user for a confirmation to clear the stud counter.
- To cancel the resetting of the stud counter, simply press NO on the screen.
- To confirm the resetting of the stud counter, simply press YES on the screen.

# SCREEN OPERATION

## Screen Status Indicators



Status Indicator	Description	Solution
OVERTEMP	Unit Has Exceeded Temperature Threshold	Unit needs to cool down before more welds can be made. Please allow the unit to cool down and clear the overtemp warning.
UNDER VOLTAGE	Insufficient Input Power	Unit has detected insufficient supply power. Connect the unit to a more stable power supply.
DC LIMIT ON	Duty Cycle Limiter Activated	Protects capacitor from overheating by limiting the user to a maximum average duty cycle. <b><u>This protection only activates when the set point of the welder is above 85V. Below 85V there is no limitation to the duty cycle of the unit.</u></b>
ERR: CHRГ TIME	Max Charge Time Exceeded	Unit has taken too long to charge and there may be an issue with the capacitor. With unit powered down ensure that all connectors and connections are tight.
ERR: OUTPUT	Capacitor Short Detection	Capacitor is not charging properly and the outputs may be shorted. Check the unit for damage as well as the SCR for a short circuit.

# SETUP AND WELDING

---

## Connecting the Welding Leads

1. Connect the stud gun weld cable into the gun terminal socket on the front of the welding unit. The cable end plug has a flat which aligns with a dot on the panel mount socket. Secure the connector into the panel mount socket, and then turn it clockwise until it locks into proper position. **Failure to properly make these connections could result in damage to the connectors.**
2. Connect the weld gun control cable into the center socket connector. The control cable plug has a large pin and a small pin that match the socket on the unit. Push the plug firmly into the socket and twist clockwise to secure the plug into the correct position.
3. Connect the ground clamp into the ground terminal socket on the front of the unit, this connection is identical to step 1.



## Connecting the Ground Clamp

1. Prior to securing the clamp, make certain that the contact area is free of rust, paint, grease, or any other impurities to ensure a good ground connection.
2. Attach the clamp of the welding ground lead to the work piece.



# SETUP AND WELDING

---

## Selecting the Proper Stud Collet (Stud Holder)



Listed below are the common collet styles, the choice between these setups is usually a matter of personal preference

1. The B collet which is a two-piece assembly (collet and insert). The insert determines how much of the stud is engaged in the collet.
2. The CI (Collet Insert) which is a single part and the amount of the stud that is engaged is predetermined.
3. Standard Adjustable Chucks have an adjustable internal screw to manually adjust for the engagement of the stud.

The collet sizes are based on the diameter of the stud to be welded.

## CD Stud Gun Setup

1. Place the collet into the collet adapter of the stud gun and set the locking screws to hold the collet in place.
2. Mount the two legs and foot piece onto the stud gun. The collet should be centered through the opening of the foot piece.
3. Insert the stud to be welded into the collet.
4. Adjust the leg and foot piece by sliding it into position until approximately 1/8" of the stud protrudes from beyond the foot piece. Lock legs in place with the set screws.
5. The tension setting is adjusted by turning the adjustment cap on the back of the stud gun. On the side of the stud gun is the tension setting indicator, this displays the tension setting of the internal spring.
6. The spring tension setting of the stud gun will vary depending on the application. Generally, mild steel and stainless steel should be set in the 1 to 2 range. Aluminum and other nonferrous metals will require settings in the 3 to 5 range.



# SETUP AND WELDING

---

## Powering On the Welder

When **all of the previous setup steps** in this manual are complete the welder can be powered on.


1. Ensure that the power cord is connected to the power cord socket and the supply power.
2. Check the 10A fuse below the ON/OFF switch located on the side of the unit.
3. Use the ON/OFF switch to power the unit on.

## Voltage Selection

- The voltage is determined by the diameter of the stud and the base material thickness. The unit is programmed with the recommended voltage settings for various stud sizes. **Fine tuning the voltage for each application from this starting point is recommended.**
- Setting the required weld voltage is achieved by selecting the desired stud size on the screen or manually setting the voltage by using the + or - arrows.
- Fast voltage selection can be done from the voltage mode screen. This will replace the preset values on the screen with voltages in increments of 10V and can be manually adjusted by using the arrows.

## Testing the Weld Settings


1. After performing all of the setup steps listed in this manual, it is recommended that several test welds be performed with the same diameter stud and base material used for the application. This will verify that all of the settings are correct to achieve the desired results.
2. Welding is done by placing the stud into the collet and pressing the stud gun to the work piece.
3. Hold the gun perpendicular to the work piece, align the stud to the desired location, press down so that the foot piece is flush with the base material, and squeeze the trigger.
4. Spreading the collet tines when lifting the stud gun from the welded stud will shorten the life of the collet and will eventually create an undesirable weld. **For maximum collet life remove the stud gun from the welded stud by pulling the stud gun straight off of the welded stud.**
5. Properly welded studs are tested by either torquing or bending the stud. Using either method the threaded portion of the stud may break. However, the welded flange of the stud should stay in place. Additionally, if the base material is very thin, a full slug the diameter of the flange will pull from the base metal.



## Inspecting the Weld

1. Visually inspect the weld. If there is a significant amount of splatter then the weld is too hot, lower the voltage. If there is no splatter then the weld is too cold, increase the voltage.
2. A good weld will result in a small, visible, and 360° flashing surrounding the flange of the stud. If there is weld flash on only one side of the base of the flange, this is called “arc blow,” and can be solved by repositioning the ground clamp or using a dual ground clamp.

# CD GUN EXPLODED VIEW




PARTS LIST			
ITEM	QTY	PART No.	DESCRIPTION
1	1	SMG-100L	CD GUN BODY LEFT HALF
2	1	SMG-100R	CD GUN BODY RIGHT HALF
3	1	SMG-101	CD GUN INTERNAL CABLE CONNECTOR
4	1	SMG-102	CD GUN BEARING
5	1	SMG-103	CD GUN BELLOWS
6	1	SMG-104	CD GUN SHAFT
7	1	SMG-105	CD GUN RETAINING NUT
8	1	SMG-106	CD GUN STRAIN RELIEF
9	1	SMG-107	CD GUN TRIGGER SWITCH
10	1	SMG-108	CD GUN SPRING LIGHT COMPRESSION
11	1	SMG-109	CD GUN SPRING HEAVY COMPRESSION
12	1	SMG-110	CD GUN SPRING ADJUSTMENT LABEL
13	1	SMG-111	CD GUN SPRING ADJUSTMENT BLOCK
14	1	SMG-112	CD GUN SPRING ADJUSTMENT SCREW
15	1	SMG-114	CD GUN BACK CAP
16	1	SMG-115	CD GUN LOCKING RING RETAINER
17	1	SMG-117	CD GUN FRONT CAP
18	2	SMG-HDWR-1	#8-32X.375 SOCKET HEAD CAP SCREW
19	2	SMG-HDWR-2	#10-24X.313 HEX SET SCREW
20	1	SMG-HDWR-3	#6-32X.375 HEX SET SCREW
21	1	SMG-HDWR-4	#10-32X.375 CAP HEAD SCREW

19-Sep-12

# CAPACITOR DISCHARGE ACCESSORIES


## "B" COLLETS

STUD DIA	PART NO.
3 MM	CDB-003M
14 GA	CDB-008
12 GA & #4	CDB-010
1/8 GA & #5	CDB-012
10 GA & #6	CDB-013
4 MM	CDB-004M
#8	CDB-015
#10	CDB-018
5 MM	CDB-005M
6 MM	CDB-006M
.215	CDB-021
1/4	CDB-025
5/16	CDB-031
8 MM	CDB-008M
3/8	CDB-037
10 MM	CDB-010M




## SOYER COLLETS

STUD DIA.	PART NO.
#6	CDBS-013
4 MM	CDBS-004M
#8	CDBS-015
#10	CDBS-018
5 MM	CDBS-005M
6 MM	CDBS-006M
1/4	CDBS-025
5/16	CDBS-031



## CD WELDING LEGS

LENGTH	DIA.	PART NO.
7"	5/16	L-03107
9"	5/16	L-03109
14"	5/16	L-03114
18"	5/16	L-03118
5/16 LEG WASHER		L-031-1
5/16 LEG SCREW		L-031-2
3/8 LEG WASHER		L-037-1
3/8 LEG SCREW		L-037-2




# CAPACITOR DISCHARGE ACCESSORIES

## ONE PIECE CONTACT/MAGNETIC CHUCK

### **PART NO.**

039-613




## MAGNETIC CHUCK

<b>PART NO.</b>	<b>DESCRIPTION</b>
035-301	COMPLETE ASSY
017-633	MAGNET ONLY
029-615	CONDUCTOR PLATE
039-609	INSUL. TUBE
039-610	INSUL. DISC
SCREW	10-32 X 7/8



## “B” COLLETS PROTECTOR

<b>STUD SIZE</b>	<b>PART NO.</b>
14 GA X 12 GA	028-837
10 GA	028-838
BODY ONLY	028-836
12 GA INSERT	028-834
10 GA INSERT	028-835



## “B” STOP

<b>STUD LENGTH</b>	<b>STOP LENGTH</b>	<b>PART NO.</b>
1/4	1-1/4	033-781
3/8	1-1/8	033-782
1/2	1”	033-783
5/8	7/8	033-784
3/4	3/4	033-785
7/8	5/8	033-775
1”	1/2	033-776
1-1/8	3/8	033-777
1-1/4	1/4	033-778
1-3/8 (BUTTON STOP)	1/8	033-779
UNIVERSAL		033-780



**SHORT BUTTON STOP**



**UNIVERSAL “B” STOP**

# CAPACITOR DISCHARGE ACCESSORIES

## COLLETS INSERTS FOR WELD STUDS



### STUD DIA.

### X DEPTH

### PART NO.

#4 X 1/4	CI-010-025
#4 X 3/8	CI-010-037
#4 X 1/2	CI-010-050
#4 X 1"	CI-010-100
#6X 1/4	CI-013-025
#6 X 3/8	CI-013-037
#6 X 1/2	CI-013-050
#6 X 5/8	CI-013-062
#6 X 3/4	CI-013-075
#6X 1"	CI-013-100
10GA X 1/2	CI-014-050
10GA X 3/4	CI-014-075
10GA X 1	CI-014-100
#8X 1/4	CI-015-025
#8 X 3/8	CI-015-037
#8 X 1/2	CI-015-050
#8 X 5/8	CI-015-062
#8 X 3/4	CI-015-075
#8X 1"	CI-015-100
#10 X 1/4	CI-018-025
#10 X 3/8	CI-018-037
#10 X 1/2	CI-018-050
#10 X 5/8	CI-018-062
#10 X 3/4	CI-018-075
#10X 1"	CI-018-100
1/4 X 1/4	CI-025-025
1/4 X 3/8	CI-025-037
1/4 X 1/2	CI-025-050
1/4 X 5/8	CI-025-062
1/4 X 3/4	CI-025-075
1/4 X 1"	CI-025-100
5/16 X 3/8	CI-031-037
5/16 X 1/2	CI-031-050
5/16 X 5/8	CI-031-062
5/16 X 3/4	CI-031-075
5/16 X 1"	CI-031-100
3/8 X 1/2	CI-037-050
3/8 X 3/4	CI-037-075
3/8 X 1"	CI-037-100

## CD FOOT PIECE



### PART NO.

028-833

## STANDARD SPARK SHIELD



### STUD RANGE

14 GA – #6

#8 – 3/8

### PART NO.

033-764

033-765

## VENTED SPARK SHIELD



### STUD RANGE

14 GA – 10 GA

#6 – 3/8

### PART NO.

033-769

033-769L

## TEMPLATE TUBE ADAPTOR



### TEMPLATE I.D.

1" DIA.

30MM

### PART NO.

039-481

80-40-513